



Hitachi Vantara Cisco UCS Support Matrix

Note: Configurations added since the last matrix will be shown in **red** text.

Introduction

Use this interoperability matrix to check whether a proposed Cisco UCS configuration is supported.

If a combination does not appear on the OS support matrix, the customer's Hitachi Vantara Sales Engineer (SE) or other Hitachi Vantara field service employee must submit an Interoperability Support Request in order to gain support for the new configuration.

Legal Disclaimer

This information is subject to change without notice. The information contained in this document is provided by Hitachi Vantara for general information purposes only and is based on information as of the date of distribution (indicated by the date above). Hitachi Vantara makes no express or implied warranties of any kind whatsoever regarding the contents of this Document or the performance of the products referred to in these documents and Hitachi Vantara expressly disclaims all warranties including, without limitation, the implied warranties of satisfactory quality, merchantability or fitness for a particular purpose, the statutory warranty against infringement, and any warranty of title. Hitachi Vantara will have no liability whatsoever for any direct loss or damage (but excluding any liability for death, personal injury or fraudulent misrepresentation) or for any indirect, special, incidental or consequential damages, including but not limited to loss of data or records, lost profits or other economic loss, arising out of or in connection with the use of this information even if such loss was foreseeable or Hitachi Vantara had been advised of the possibility of such loss.

Hitachi Vantara Cisco UCS Support Matrix for Hitach Vantara VSP F1500, G1x00, Fxx0, Gxx0

Operating System (All X64 architecture)	CNA model	CNA driver	UCS Switch model	UCS Switch firmware	SAN switch model	SAN switch firmware
Red Hat Enterprise Linux 7.5	Cisco UCS 1440/1480	v1.6.0.34	Cisco UCS 6332-16UP	v4.0(1c)	Cisco MDS 9706	v8.3(1)
	Cisco UCS 1340/1380	v1.6.0.44	Cisco UCS 6332-16UP	v4.0(1c)	Cisco MDS 9706	v8.3(1)
SUSE Linux Enterprise Server 12 SP4	Cisco UCS 1440/1480	v1.6.0.34	Cisco UCS 6332-16UP	v4.0(1c)	Cisco MDS 9706	v8.3(1)
	Cisco UCS 1340/1380	v1.6.0.47	Cisco UCS 6332-16UP	v4.0(1c)	Cisco MDS 9706	v8.3(1)
VMWare ESXi 6.5 UP2	Cisco UCS 1440/1480	v1.6.0.44	Cisco UCS 6332-16UP	v4.0(1b)	Cisco MDS 9706	v8.3(1)
			Cisco UCS 6454	v4.0(1b)		
VMWare ESXi 6.7 UP1	Cisco UCS 1440/1480	v4.0.0.14	Cisco UCS 6332-16UP	v4.0(1b)	Cisco MDS 9706	v8.3(1)
			Cisco UCS 6454	v4.0(1b)		