



AIX Support Matrix

Hitachi VSP 5x00, G1x00, F1500, E990, Gxx0, Fxx0, HUS VM

Note: Configurations added since the last matrix will be shown in red text.

Introduction

Use this interoperability matrix to check whether a proposed customer configuration is supported. Each tab contains a set of components that together comprise an Hitachi Vantara-supported solution. This includes operating system (OS) and maintenance release, host bus adapter (HBA), HBA driver, and storage area network (SAN) switches, both Fibre channel (FC), Fibre channel over Ethernet (FCoE).

Note: The arrays supported now include the VSP E990.

Note on the 16 & 32 Gb Interfaces:

- The 32Gb interface is only available on the VSP 5x00, E990, GX00 and FX00 arrays. It is supported with both 16 & 32Gb SFPs and operates at a maximum of 32Gbps.
- The HUS VM does not have a 16Gb FC interface.
- With SVOS 7, for Direct connection to 16Gb or 32Gb FC you must set the storage port to Fabric = OFF and Connection Type P-to-P (Point to Point)

If a combination does not appear on the OS support matrix, the customer's Hitachi Vantara Sales Engineer (SE) or other Hitachi field service employee must submit an Interoperability Support Request in order to gain support for the new configuration.

Legal Disclaimer

This information is subject to change without notice. The information contained in this document is provided by Hitachi Vantara for general information purposes only and is based on information as of the date of distribution (indicated by the date above). Hitachi Vantara makes no express or implied warranties of any kind whatsoever regarding the contents of this Document or the performance of the products referred to in these documents and Hitachi Vantara expressly disclaims all warranties including, without limitation, the implied warranties of satisfactory quality, merchantability or fitness for a particular purpose, the statutory warranty against infringement, and any warranty of title. Hitachi Vantara will have no liability whatsoever for any direct loss or damage (but excluding any liability for death, personal injury or fraudulent misrepresentation) or for any indirect, special, incidental or consequential damages, including but not limited to loss of data or records, lost profits or other economic loss, arising out of or in connection with the use of this information even if such loss was foreseeable or Hitachi Vantara had been advised of the possibility of such loss.

VSP 5x00, G1x00, F1500, E990, Gxx0, Fxx0 support for AIX 7.2 TL04

FC Storage Interface			
Host Bus Adapters (FC-HBA)/Converged Network Adapters (CNA)			
Manufacturer	Models	Driver Versions	Notes
IBM	ENOA, ENOB	Bundled	
	ENOG, ENOY	Bundled	
	EN1A, EN1B	Bundled	
FC Switches			
Manufacturer	Models	Firmware Versions	Notes
Brocade	6505, 6510, 6520, 7840, DCX 8510	v8.2.0a - v8.2.0b, v8.2.1a - v8.2.1e, v8.2.2 v8.2.2c	Brocade FOS v8.2.0 and v8.2.1 are not supported.
	G610	v8.2.0a - v8.2.0b, v8.2.1a - v8.2.1e, v8.2.2 v8.2.2c	Brocade FOS v8.2.0 and v8.2.1 are not supported.
	G620, X6	v8.2.0a - v8.2.0b, v8.2.1a - v8.2.1e, v8.2.2 v8.2.2c	Brocade FOS v8.2.0 and v8.2.1 are not supported.
	G630	v8.2.0a - v8.2.0b, v8.2.1a - v8.2.1e, v8.2.2 v8.2.2c	Brocade FOS v8.2.0 and v8.2.1 are not supported.
	G620v2, G630v2, G720, X6 Plus, X7	v9.0.0a - v9.0.0b	
Cisco	9132T	v8.3(1) - v8.3(2)	
	9148S, 9706	v8.4(1) - v8.4(2a)	
	9148T, 9396T	v8.3(1) - v8.3(2)	
	9250i	v8.4(1) - v8.4(2a)	
	9396S	v8.4(1) - v8.4(2a)	
	9710	v8.4(1) - v8.4(2a)	
	9718	v8.4(1) - v8.4(2a)	
	9706 (32Gb), 9710 (32Gb)	v8.3(1) - v8.3(2)	
9718 (32Gb)	v8.3(2)	Cisco OS v8.3(1) is no longer supported on the 9718.	

VSP 5x00, G1x00, F1500, E990, Gxx0, Fxx0 support for AIX 7.2 TL03

FC Storage Interface			
Host Bus Adapters (FC-HBA)/Converged Network Adapters (CNA)			
Manufacturer	Models	Driver Versions	Notes
IBM	5708	Bundled	
	5729, 5735	Bundled	
	ENOA, ENOB	Bundled	
	ENOH, ENOJ	Bundled	
	ENOG, ENOY	Bundled	
	EN1A, EN1B	Bundled	
	EN1C, EN1D	Bundled	
FC Switches			
Manufacturer	Models	Firmware Versions	Notes
Brocade	6505, 6510, 6520, 7840, DCX 8510	v8.2.0a - v8.2.0b, v8.2.1a - v8.2.1e	Brocade FOS v8.2.0 & v8.2.1 are not supported.
	G610	v8.2.1a - v8.2.1e, v8.2.2 - v8.2.2c	Brocade FOS v8.2.1 is not supported.
	G620, X6	v8.2.1a - v8.2.1e, v8.2.2 - v8.2.2c	Brocade FOS v8.2.1 is not supported.
	G630	v8.2.1a - v8.2.1e, v8.2.2 - v8.2.2c	Brocade FOS v8.2.1 is not supported.
Cisco	9132T	v8.3(1) - v8.3(2)	
	9148S, 9706	v8.3(1) - v8.3(2)	
	9148T, 9396T	v8.3(1) - v8.3(2), v8.4(1) - v8.4(1a)	
	9250i	v8.3(1) - v8.3(2)	
	9396S	v8.3(1) - v8.3(2)	
	9710	v8.3(1) - v8.3(2)	
	9718	v8.3(2)	Cisco OS v8.3(1) is no longer supported on the 9718.
	9706 (32Gb), 9710 (32Gb)	v8.3(1) - v8.3(2)	
	9718 (32Gb)	v8.3(2)	Cisco OS v8.3(1) is no longer supported on the 9718.
FCOE Switches (FCF mode)			
Manufacturer	Models	Firmware Versions	Notes
Cisco	Nexus 5672up, 5672up-2248pq	v7.3(0)N1(1) - v7.3(1)N1(1)	

FCOE Storage Interface - VSP G1000 only			
Converged Network Adapters (CNA)			
Manufacturer	Models	Driver Versions	Notes
IBM	5708	Bundled	
	ENOH, ENOJ	Bundled	
FCOE Switches			
Manufacturer	Models	Firmware Versions	Notes
Any	Generic DCB IP Switch	Any DCB 10GigE FW	
Cisco	Nexus 5672up, 5672up-2248pq	v7.3(0)N1(1) - v7.3(1)N1(1)	

VSP 5x00, G1x00, F1500, Gxx0, Fxx0 support for AIX 7.2 TL02

FC Storage Interface			
Host Bus Adapters (FC-HBA)/Converged Network Adapters (CNA)			
Manufacturer	Models	Driver Versions	Notes
IBM	5708	Bundled	
	5729, 5735	Bundled	
	EN0A, EN0B	Bundled	
	EN0H, EN0J	Bundled	
	EN0G, EN0Y	Bundled	
	EN1A, EN1B	Bundled	
	EN1C, EN1D	Bundled	
FC Switches			
Manufacturer	Models	Firmware Versions	Notes
Brocade	300, 7800	v7.4.2d - v7.4.2g	
	6505, 6510, 6520, 7840, DCX 8510	v8.1.2a - v8.1.2b, v8.1.2d, v8.1.2f - v8.1.2k, v8.2.0a - v8.2.0b, v8.2.1a - v8.2.1e, v8.2.2 - v8.2.2c	Brocade FOS v8.1.2c, v8.1.2e, v8.2.0, and v8.2.1 are not supported.
	G610	v8.1.2a - v8.1.2b, v8.1.2d, v8.1.2f - v8.1.2k, v8.2.0a - v8.2.0b	Brocade FOS v8.1.2c, v8.1.2e, and v8.2.0 are not supported.
	G620, X6	v8.1.2a - v8.1.2b, v8.1.2d, v8.1.2f - v8.1.2k, v8.2.0a - v8.2.0b	Brocade FOS v8.1.2c, v8.1.2e, and v8.2.0 are not supported.
	G630	v8.2.0a - v8.2.0b	Brocade FOS v8.2.0 is not supported.
Cisco	9148, 9506 (8Gb), 9513 (8Gb)	v6.2(17) - v6.2(29) - v6.2(31), v7.3(0)D1(1) - v7.3(1)D1(1)	
	9148S, 9706	v6.2(17) - v6.2(29) - v6.2(31), v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
	9148T, 9396T	v8.3(1) - v8.3(2), v8.4(1) - v8.4(1a)	
	9250i	v6.2(17) - v6.2(29) - v6.2(31), v7.3(0)D1(1) - v7.3(1)D1(1), v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
	9396S	v6.2(17) - v6.2(29) - v6.2(31), v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
	9710	v6.2(17) - v6.2(29) - v6.2(31), v7.3(0)D1(1) - v7.3(1)D1(1), v7.3(0)DY(1), v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
	9718	v7.3(0)D1(1) - v7.3(1)D1(1), v7.3(0)DY(1), v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
	9706 (32Gb), 9710 (32Gb), 9718 (32Gb)	v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
FCOE Switches (FCF mode)			
Manufacturer	Models	Firmware Versions	Notes
Cisco	Nexus 5672up, 5672up-2248pq	v7.3(0)N1(1) - v7.3(1)N1(1)	
	Nexus 6001p-2248pq, 6001T, 6004	v7.3(0)N1(1) - v7.3(1)N1(1)	

FCOE Storage Interface - VSP G1000 only

Converged Network Adapters (CNA)

Manufacturer	Models	Driver Versions	Notes
IBM	5708	Bundled	
	ENOH, ENOJ	Bundled	

FCOE Switches

Manufacturer	Models	Firmware Versions	Notes
Any	Generic DCB IP Switch	Any DCB 10GigE FW	
Cisco	Nexus 5672up, 5672up-2248pq	v7.3(0)N1(1) - v7.3(1)N1(1)	

VSP 5x00, G1x00, F1500, Gxx0, Fxx0 support for AIX 7.2 TL01

FC Storage Interface			
Host Bus Adapters (FC-HBA)/Converged Network Adapters (CNA)			
Manufacturer	Models	Driver Versions	Notes
IBM	5708	Bundled	
	5729, 5735	Bundled	
	EN0A, EN0B	Bundled	
	EN0G, EN0Y	Bundled	
	EN1A, EN1B	Bundled	
	EN1C, EN1D	Bundled	
FC Switches			
Manufacturer	Models	Firmware Versions	Notes
Brocade	300, 7800	v7.4.2d - v7.4.2g	
	6505, 6510, 6520, 7840, DCX 8510	v7.4.2d - v7.4.2g, v8.1.2a - v8.1.2b, v8.1.2d, v8.1.2f - v8.1.2k, v8.2.0a - v8.2.0b, v8.2.1a - v8.2.1e, v8.2.2 - v8.2.2c	Brocade FOS v8.1.2c, v8.1.2e, v8.2.0, and v8.2.1 are not supported.
	G610	v8.1.2a - v8.1.2b, v8.1.2d, v8.1.2f - v8.1.2k, v8.2.0a - v8.2.0b	Brocade FOS v8.1.2c, v8.1.2e, and v8.2.0 are not supported.
	G620, X6	v8.1.2a - v8.1.2b, v8.1.2d, v8.1.2f - v8.1.2k, v8.2.0a - v8.2.0b	Brocade FOS v8.1.2c, v8.1.2e, and v8.2.0 are not supported.
Cisco	9148, 9222i, 9506 (8Gb), 9513 (8Gb)	v6.2(17) - v6.2(29) - v6.2(31), v7.3(0)D1(1) - v7.3(1)D1(1), v7.3(0)DY(1) - v7.3(1)DY(1)	
	9148S, 9706	v6.2(17) - v6.2(29) - v6.2(31), v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
	9148T, 9396T	v8.3(1) - v8.3(2), v8.4(1) - v8.4(1a)	
	9250i	v6.2(17) - v6.2(29) - v6.2(31), v7.3(0)D1(1) - v7.3(1)D1(1), v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
	9396S	v6.2(17) - v6.2(29) - v6.2(31), v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
	9710	v6.2(17) - v6.2(29) - v6.2(31), v7.3(0)D1(1) - v7.3(1)D1(1), v7.3(0)DY(1), v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
	9718	v7.3(0)D1(1) - v7.3(1)D1(1), v7.3(0)DY(1), v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
	9706 (32Gb), 9710 (32Gb), 9718 (32Gb)	v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2), v8.3(1) - v8.3(2)	

VSP G1x00, F1500, Gxx0, Fxx0, HUS VM support for AIX 7.2

FC Storage Interface			
Host Bus Adapters (FC-HBA)/Converged Network Adapters (CNA)			
Manufacturer	Models	Driver Versions	Notes
IBM	5708	Bundled	
	5729, 5735	Bundled	
	ENOA, ENOB	Bundled	
	ENOH, ENOJ	Bundled	
	ENOG, ENOY	Bundled	
FC Switches			
Manufacturer	Models	Firmware Versions	Notes
Brocade	300, 7800	v7.4.2d - v7.4.2g	
	6505, 6510, 6520, 7840, DCX 8510	v8.1.2a - v8.1.2b, v8.1.2d, v8.1.2f - v8.1.2k, v8.2.0a - v8.2.0b, v8.2.1a - v8.2.1e, v8.2.2 - v8.2.2c	Brocade FOS v8.1.2c, v8.1.2e, v8.2.0, and v8.2.1 are not supported.
	G610	v8.1.2a - v8.1.2b, v8.1.2d, v8.1.2f - v8.1.2k, v8.2.0a - v8.2.0b	Brocade FOS v8.1.2c, v8.1.2e, and v8.2.0 are not supported.
	G620, X6	v8.1.2a - v8.1.2b, v8.1.2d, v8.1.2f - v8.1.2k, v8.2.0a - v8.2.0b	Brocade FOS v8.1.2c, v8.1.2e, and v8.2.0 are not supported.
Cisco	9148, 9506 (8Gb), 9513 (8Gb)	v6.2(17) - v6.2(29) - v6.2(31), v7.3(0)D1(1) - v7.3(1)D1(1), v7.3(0)DY(1) - v7.3(1)DY(1)	
	9148S, 9706	v6.2(17) - v6.2(29) - v6.2(31), v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
	9148T, 9396T	v8.3(1) - v8.3(2), v8.4(1) - v8.4(1a)	
	9250i	v6.2(17) - v6.2(29) - v6.2(31), v7.3(0)D1(1) - v7.3(1)D1(1), v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
	9396S	v6.2(17) - v6.2(29) - v6.2(31), v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
	9710	v6.2(17) - v6.2(29) - v6.2(31), v7.3(0)D1(1) - v7.3(1)D1(1), v7.3(0)DY(1), v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
	9706 (32Gb), 9710 (32Gb), 9718 (32Gb)	v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
FCoE Switches (FCF mode)			
Manufacturer	Models	Firmware Versions	Notes
Cisco	9710 (FCoE)	v7.3(0)DY(1)	
	Nexus 5596UP, 5548up-2232pp, Nexus 5596T-2232TM-E	v7.0(0)N1(1) - v7.0(8)N1(1)	

FCOE Storage Interface - VSP G1000 only			
Converged Network Adapters (CNA)			
Manufacturer	Models	Driver Versions	Notes
IBM	5708	Bundled	
	ENOH	Bundled	
FCOE Switches			
Manufacturer	Models	Firmware Versions	Notes
Any	Generic DCB IP Switch	Any DCB 10GigE FW	
Cisco	Nexus 5596UP, 5548up-2232pp, Nexus 5596T-2232TM-E	v7.0(0)N1(1) - v7.0(8)N1(1)	

VSP 5x00, G1x00, F1500, E990, Gxx0, Fxx0 support for AIX 7.1 TL05

FC Storage Interface			
Host Bus Adapters (FC-HBA)/Converged Network Adapters (CNA)			
Manufacturer	Models	Driver Versions	Notes
IBM	5708	Bundled	
	5729, 5735	Bundled	
	EN0A, EN0B	Bundled	
	EN0H, EN0J	Bundled	
	EN0G, EN0Y	Bundled	
	EN1A, EN1B	Bundled	
	EN1C, EN1D	Bundled	
FC Switches			
Manufacturer	Models	Firmware Versions	Notes
Brocade	6505, 6510, 6520, 7840, DCX 8510	v8.1.2a - v8.1.2b, v8.1.2d, v8.1.2f - v8.1.2k, v8.2.0a - v8.2.0b, v8.2.1a - v8.2.1e, v8.2.2 - v8.2.2c	Brocade FOS v8.1.2c, v8.1.2e, v8.2.0, and v8.2.1 are not supported.
	G610	v8.1.2a - v8.1.2b, v8.1.2d, v8.1.2f - v8.1.2k, v8.2.0a - v8.2.0b	Brocade FOS v8.1.2c, v8.1.2e, and v8.2.0 are not supported.
	G620, X6	v8.1.2a - v8.1.2b, v8.1.2d, v8.1.2f - v8.1.2k, v8.2.0a - v8.2.0b	Brocade FOS v8.1.2c, v8.1.2e, and v8.2.0 are not supported.
	G630	v8.2.0a - v8.2.0b	Brocade FOS v8.2.0 is not supported.
	G620v2, G630v2, G720, X6 Plus, X7	v9.0.0a - v9.0.0b	
Cisco	9148, 9506 (8Gb), 9513 (8Gb)	v6.2(17) - v6.2(29) - v6.2(31), v7.3(0)D1(1) - v7.3(1)D1(1)	
	9132T	v8.4(1) - v8.4(2a)	
	9148S, 9706	v6.2(17) - v6.2(29) - v6.2(31), v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2), v8.4(1) - v8.4(1a)	
	9148T, 9396T	v8.3(1) - v8.3(2), v8.4(1) - v8.4(1a)	
	9250i	v6.2(17) - v6.2(29) - v6.2(31), v7.3(0)D1(1) - v7.3(1)D1(1), v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
	9396S	v6.2(17) - v6.2(29) - v6.2(31), v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
	9710	v6.2(17) - v6.2(29) - v6.2(31), v7.3(0)D1(1) - v7.3(1)D1(1), v7.3(0)DY(1), v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
	9718	v7.3(0)D1(1) - v7.3(1)D1(1), v7.3(0)DY(1), v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
	9706 (32Gb), 9710 (32Gb), 9718 (32Gb)	v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
FCOE Switches (FCF mode)			
Manufacturer	Models	Firmware Versions	Notes
Cisco	Nexus 5672up, 5672up-2248pq	v7.3(0)N1(1) - v7.3(1)N1(1)	

FCOE Storage Interface - VSP G1000 only

Converged Network Adapters (CNA)

Manufacturer	Models	Driver Versions	Notes
IBM	5708	Bundled	
	EN0H, EN0J	Bundled	

FCOE Switches

Manufacturer	Models	Firmware Versions	Notes
Any	Generic DCB IP Switch	Any DCB 10GigE FW	
Cisco	Nexus 5672up, 5672up-2248pq	v7.3(0)N1(1) - v7.3(1)N1(1)	

VSP 5x00, G1x00, F1500, Gxx0, Fxx0 support for AIX 7.1 TL04

FC Storage Interface			
Host Bus Adapters (FC-HBA)/Converged Network Adapters (CNA)			
Manufacturer	Models	Driver Versions	Notes
IBM	5708	Bundled	
	5729, 5735	Bundled	
	ENOA, ENOB	Bundled	
	ENOH, ENOJ	Bundled	
	ENOG, ENOY	Bundled	
FC Switches			
Manufacturer	Models	Firmware Versions	Notes
Brocade	300, 7800	v7.4.2d - v7.4.2g	
	6505, 6510, 6520, 7840, DCX 8510	v8.1.2a - v8.1.2b, v8.1.2d, v8.1.2f - v8.1.2k, v8.2.0a - v8.2.0b, v8.2.1a - v8.2.1e, v8.2.2 - v8.2.2c	Brocade FOS v8.1.2c, v8.1.2e, v8.2.0, and v8.2.1 are not supported.
	G610	v8.1.2a - v8.1.2b, v8.1.2d, v8.1.2f - v8.1.2k, v8.2.0a - v8.2.0b	Brocade FOS v8.1.2c, v8.1.2e, and v8.2.0 are not supported.
	G620, X6	v8.1.2a - v8.1.2b, v8.1.2d, v8.1.2f - v8.1.2k, v8.2.0a - v8.2.0b	Brocade FOS v8.1.2c, v8.1.2e, and v8.2.0 are not supported.
	G630	v8.2.0a - v8.2.0b	Brocade FOS v8.2.0 is not supported.
Cisco	9148, 9506 (8Gb), 9513 (8Gb)	v6.2(17) - v6.2(29) - v6.2(31), v7.3(0)D1(1) - v7.3(1)D1(1)	
	9148S, 9706	v6.2(17) - v6.2(29) - v6.2(31), v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
	9148T, 9396T	v8.3(1) - v8.3(2), v8.4(1) - v8.4(1a)	
	9250i	v6.2(17) - v6.2(29) - v6.2(31), v7.3(0)D1(1) - v7.3(1)D1(1), v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
	9396S	v6.2(17) - v6.2(29) - v6.2(31), v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
	9710	v6.2(17) - v6.2(29) - v6.2(31), v7.3(0)D1(1) - v7.3(1)D1(1), v7.3(0)DY(1), v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
	9718	v7.3(0)D1(1) - v7.3(1)D1(1), v7.3(0)DY(1), v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
	9706 (32Gb), 9710 (32Gb), 9718 (32Gb)	v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
FCOE Switches (FCF mode)			
Manufacturer	Models	Firmware Versions	Notes
Cisco	9710 (FCoE)	v7.3(0)DY(1)	
	Nexus 5596UP, 5548up-2232pp, Nexus 5596T-2232TM-E	v7.0(0)N1(1) - v7.0(8)N1(1)	

FCOE Storage Interface - VSP G1000 only			
Converged Network Adapters (CNA)			
Manufacturer	Models	Driver Versions	Notes
IBM	5708	Bundled	
	EN0H, EN0J	Bundled	
FCOE Switches			
Manufacturer	Models	Firmware Versions	Notes
Any	Generic DCB IP Switch	Any DCB 10GigE FW	
Cisco	Nexus 5596UP, 5548up-2232pp, Nexus 5596T-2232TM-E	v7.0(0)N1(1) - v7.0(8)N1(1)	

VSP G1x00, F1500, Gxx0, Fxx0, HUS VM support for AIX 7.1 TL03

FC Storage Interface			
Host Bus Adapters (FC-HBA)/Converged Network Adapters (CNA)			
Manufacturer	Models	Driver Versions	Notes
IBM	44X1940, 44X1942, 44X1945, 44X1947	Bundled	
	46M6140	Bundled	
	5708	Bundled	
	5729, 5735	Bundled	
	ENOA, ENOB	Bundled	
	ENOH, ENOJ	Bundled	
	ENOG, ENOY	Bundled	
FC Switches			
Manufacturer	Models	Firmware Versions	Notes
Brocade	300, 7800	v7.4.2d - v7.4.2g	
	6505, 6510, 6520, 7840, DCX 8510	v8.1.2a - v8.1.2b, v8.1.2d, v8.1.2f - v8.1.2k	Brocade FOS v8.1.2c, and v8.1.2e are not supported.
	G610	v8.1.2a - v8.1.2b, v8.1.2d, v8.1.2f - v8.1.2k	Brocade FOS v8.1.2c, and v8.1.2e are not supported.
	G620, X6	v8.1.2a - v8.1.2b, v8.1.2d, v8.1.2f - v8.1.2k	Brocade FOS v8.1.2c, and v8.1.2e are not supported.
Cisco	9148, 9506 (8Gb), 9513 (8Gb)	v6.2(17) - v6.2(29) - v6.2(31), v7.3(0)D1(1) - v7.3(1)D1(1)	
	9148S, 9706	v6.2(17) - v6.2(29) - v6.2(31), v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
	9148T, 9396T	v8.3(1) - v8.3(2), v8.4(1) - v8.4(1a)	
	9250i	v6.2(17) - v6.2(29) - v6.2(31), v7.3(0)D1(1) - v7.3(1)D1(1), v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
	9396S	v6.2(17) - v6.2(29) - v6.2(31), v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
	9710	v6.2(17) - v6.2(29) - v6.2(31), v7.3(0)D1(1) - v7.3(1)D1(1), v7.3(0)DY(1), v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
	9718	v7.3(0)D1(1) - v7.3(1)D1(1), v7.3(0)DY(1), v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
	9706 (32Gb), 9710 (32Gb), 9718 (32Gb)	v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
FCOE Switches (FCF mode)			
Manufacturer	Models	Firmware Versions	Notes
Any	Generic DCB IP Switch	Any DCB 10GigE FW	
Cisco	9710 (FCoE)	v7.3(0)DY(1)	
	Nexus 6001P, 6001p-2248pq, 6001T, 6004	v7.0(0)N1(1) - v7.0(7)N1(1), v7.3(0)N1(1) - v7.3(1)N1(1)	

FCOE Storage Interface - VSP G1000 only			
Converged Network Adapters (CNA)			
Manufacturer	Models	Driver Versions	Notes
IBM	ENOH	Bundled	
FCOE Switches			
Manufacturer	Models	Firmware Versions	Notes
Any	Generic DCB IP Switch	Any DCB 10GigE FW	
Cisco	Nexus 6001P, 6001p-2248pq, 6001T, 6004	v7.0(0)N1(1), v7.0(1)N1(1), v7.0(2)N1(1), v7.0(3)N1(1) - v7.0(8)N1(1)	

VSP G1x00, F1500, Gxx0, Fxx0, HUS VM support for AIX 7.1 TL02

FC Storage Interface			
Host Bus Adapters (FC-HBA)/Converged Network Adapters (CNA)			
Manufacturer	Models	Driver Versions	Notes
IBM	44X1940, 44X1942, 44X1945, 44X1947	Bundled	
	46M6140	Bundled	
	5708	Bundled	
	5729, 5735	Bundled	
	95Y2391	Bundled	
	ENOA, ENOB	Bundled	
	ENOH, ENOJ	Bundled	
	ENOG, ENOY	Bundled	
FC Switches			
Manufacturer	Models	Firmware Versions	Notes
Brocade	300, 7800	v7.4.2d - v7.4.2g	
	6505, 6510, 6520, 7840, DCX 8510	v8.1.2a - v8.1.2b, v8.1.2d, v8.1.2f - v8.1.2k	Brocade FOS v8.1.2c, and v8.1.2e are not supported.
	G610	v8.1.2a - v8.1.2b, v8.1.2d, v8.1.2f - v8.1.2k	Brocade FOS v8.1.2c, and v8.1.2e are not supported.
	G620, X6	v8.1.2a - v8.1.2b, v8.1.2d, v8.1.2f - v8.1.2k	Brocade FOS v8.1.2c, and v8.1.2e are not supported.
Cisco	9148, 9506 (8Gb), 9513 (8Gb)	v6.2(17) - v6.2(29) - v6.2(31), v7.3(0)D1(1) - v7.3(1)D1(1)	
	9148S, 9706	v6.2(17) - v6.2(29) - v6.2(31), v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2), v8.3(1) - v8.3(2)	
	9148T, 9396T	v8.3(1) - v8.3(2), v8.4(1) - v8.4(1a)	
	9250i	v6.2(17) - v6.2(29) - v6.2(31), v7.3(0)D1(1) - v7.3(1)D1(1), v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
	9396S	v6.2(17) - v6.2(29) - v6.2(31), v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
	9710	v6.2(17) - v6.2(29) - v6.2(31), v7.3(0)D1(1) - v7.3(1)D1(1), v7.3(0)DY(1), v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
	9718	v7.3(0)D1(1) - v7.3(1)D1(1), v7.3(0)DY(1), v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
	9706 (32Gb), 9710 (32Gb), 9718 (32Gb)	v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
IBM	88Y6374	v7.2.0b1	supports limited to IBM adapter 95Y2391 only
FCoE Switches (FCF mode)			
Manufacturer	Models	Firmware Versions	Notes
Cisco	9710 (FCoE)	v7.3(0)DY(1)	

FCoE Storage Interface - VSP G1000 only			
Converged Network Adapters (CNA)			
Manufacturer	Models	Driver Versions	Notes
IBM	5708	Bundled	
FCoE Switches			
Manufacturer	Models	Firmware Versions	Notes
Any	Generic DCB IP Switch	Any DCB 10GigE FW	

VSP G1x00, F1500, Gxx0, Fxx0, HUS VM support for AIX 7.1 TL01

FC Storage Interface			
Host Bus Adapters (FC-HBA)/Converged Network Adapters (CNA)			
Manufacturer	Models	Driver Versions	Notes
IBM	5729, 5735	Bundled	
FC Switches			
Manufacturer	Models	Firmware Versions	Notes
Brocade	300, 7800	v7.4.2d - v7.4.2g	
	6505, 6510, 6520, 7840, DCX 8510	v8.1.2a - v8.1.2b, v8.1.2d, v8.1.2f - v8.1.2k	Brocade FOS v8.1.2c, and v8.1.2e are not supported.
	G610	v8.1.2a - v8.1.2b, v8.1.2d, v8.1.2f - v8.1.2k	Brocade FOS v8.1.2c, and v8.1.2e are not supported.
	G620, X6	v8.1.2a - v8.1.2b, v8.1.2d, v8.1.2f - v8.1.2k	Brocade FOS v8.1.2c, and v8.1.2e are not supported.
Cisco	9148, 9506 (8Gb), 9513 (8Gb)	v6.2(17) - v6.2(29) - v6.2(31), v7.3(0)D1(1) - v7.3(1)D1(1)	
	9148S, 9706	v6.2(17) - v6.2(29) - v6.2(31), v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
	9148T, 9396T	v8.3(1) - v8.3(2), v8.4(1) - v8.4(1a)	
	9250i	v6.2(17) - v6.2(29) - v6.2(31), v7.3(0)D1(1) - v7.3(1)D1(1), v8.1(1) - v8.1(1b), v8.2(1) -	
	9396S	v6.2(17) - v6.2(29) - v6.2(31), v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
	9710	v6.2(17) - v6.2(29) - v6.2(31), v7.3(0)D1(1) - v7.3(1)D1(1), v7.3(0)DY(1), v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
	9706 (32Gb), 9710 (32Gb), 9718 (32Gb)	v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	

VSP G1x00, F1500, Gxx0, Fxx0, HUS VM support for AIX 7.1

FC Storage Interface			
Host Bus Adapters (FC-HBA)/Converged Network Adapters (CNA)			
Manufacturer	Models	Driver Versions	Notes
IBM	5729, 5735	Bundled	
	EN0G, EN0Y	Bundled	
FC Switches			
Manufacturer	Models	Firmware Versions	Notes
Brocade	300, 7800	v7.4.2d - v7.4.2g	
	6505, 6510, 6520, 7840, DCX 8510	v8.1.2a - v8.1.2b, v8.1.2d, v8.1.2f - v8.1.2k	Brocade FOS v8.1.2c, and v8.1.2e are not supported.
	G610	v8.1.2a - v8.1.2b, v8.1.2d, v8.1.2f - v8.1.2k	Brocade FOS v8.1.2c, and v8.1.2e are not supported.
	G620, X6	v8.1.2a - v8.1.2b, v8.1.2d, v8.1.2f - v8.1.2k	Brocade FOS v8.1.2c, and v8.1.2e are not supported.
Cisco	9148, 9506 (8Gb), 9513 (8Gb)	v6.2(17) - v6.2(29) - v6.2(31), v7.3(0)D1(1) - v7.3(1)D1(1)	
	9148S, 9706	v6.2(17) - v6.2(29) - v6.2(31), v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
	9148T, 9396T	v8.3(1) - v8.3(2), v8.4(1) - v8.4(1a)	
	9250i	v6.2(17) - v6.2(29) - v6.2(31), v7.3(0)D1(1) - v7.3(1)D1(1), v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
	9396S	v6.2(17) - v6.2(29) - v6.2(31), v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
	9710	v6.2(17) - v6.2(29) - v6.2(31), v7.3(0)D1(1) - v7.3(1)D1(1), v7.3(0)DY(1), v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	
	9706 (32Gb), 9710 (32Gb), 9718 (32Gb)	v8.1(1) - v8.1(1b), v8.2(1) - v8.2(2)	