



HCP Support Matrix

Hitachi VSP 5X00 G1x00, F1500, Gx00, Fxx0, VSP, and HUS VM , AMS 2500

Introduction

Use this

interoperability matrix to check whether a proposed customer configuration is supported. Each tab contains a set of components that together comprise an HDS-supported solution. This includes operating system (OS) and maintenance release, host bus adapter (HBA), HBA driver, and storage area network (SAN) switches, both Fibre channel (FC) and Fibre channel over Ethernet (FCoE).

In the sample datapath below, a customer configuration is supported if that particular HBA and driver, switch and switch firmware combinations both appear on the Windows Server 2012 R2 support matrix.

For example: Windows Server 2012 R2 host that has an Emulex LPe12000/12002 HBA using driver v2.76.002.001 connected to a Brocade DCX SAN switch with FOS v7.2.1 installed.

If a combination does not appear on the OS support matrix, the customer's Hitachi Data Systems Sales Engineer (SE) or other HDS field service employee must submit an Interoperability Support Request in order to gain support for the new configuration.

Note that in some cases a component (HBA, driver, switch, switch firmware version) may no longer be supported (end of service life, EOSL) in which case the customer should choose components that are already supported from the matrix. Click on a tab to view associated components.

Gxx0 refers to : G900,G800,G700, G600, G400,G370,G350 and G200

Fxx0 refers to : F900,F800, F700,F600, F400,F370,F350

G1x00 refers to : G1500 and G1000

5X00 refers to : 5500, 5500H, 5100,5100H

Legal Disclaimer

This information is subject to change without notice. The information contained in this document is provided by HDS for general information purposes only and is based on information as of the date of distribution (indicated by the date above). HDS makes no express or implied warranties of any kind whatsoever regarding the contents of this Document or the performance of the products referred to in these documents and HDS expressly disclaims all warranties including, without limitation, the implied warranties of satisfactory quality, merchantability or fitness for a particular purpose, the statutory warranty against infringement, and any warranty of title. HDS will have no liability whatsoever for any direct loss or damage (but excluding any liability for death, personal injury or fraudulent misrepresentation) or for any indirect, special, incidental or consequential damages, including but not limited to loss of data or records,

**VSP 5X00, G1x00, F1500, Gxx0, Fxx0
support for :HCP 8.1.1**

Host Bus Adapters (FC-HBA)/Converged Network Adapters (CNA)

Manufacturer	Models	Driver Version	Notes
Emulex	LPe12002	Bundled	

FC Switches

Manufacturer	Models	Firmware Versions	Notes
Brocade	G630	v8.2.0a - v8.2.0b	
Cisco	Cisco MDS 9718 (32Gb)	v8.3(2)	